

ROCKY FLATS ENVIRONMENTAL

TECHNOLOGY SITE

Manual No.: Procedure No.: 5-21000-OPS-AP

SHE

Page:

Table of Contents, Rev 7 1 of 2

EMD OPERATING PROCEDURES Effe

Effective Date:

09/28/94

MANUAL VOL. VI: AIR

Organization:

Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
VOLUME III: GEOTECHNICAL (GT)
VOLUME IV: SURFACE WATER (SW)
VOLUME V: ECOLOGY (EE)
VOLUME VI: AIR (AP)

TABLE OF CONTENTS FOR VOLUME VI: AIR

Procedure <u>No.</u>	<u>Title</u>	Rev. <u>No</u> .	Effective <u>Date</u>				
AP.01	4-C97-ENV-AQ.01 Effluent Tritium Sample Collection	0*	03/18/94				
* This docume	ent is a complete revision of document 5-21000-OPS-	AP.01,R0.					
AP.02	4-C98-ENV-AQ.02 Tritium Sampler Calibration	0*	03/18/94				
• This document is a complete revision of document 5-21000-OPS-AP.02,R0.							
•94-DMR-001850	New Calibration Rotometer	0	09/28/94				
AP.03	4-C83-ENV-AQ.03 Effluent Air Radioparticulate Sample Collection	0*	06/01/94				
*This document is a complete revision of document 5-21000-OPS-AP.03,R0.							
•94-DMR-001845	Effluent Travelers & COC Sheets Collection	0	09/27/94				
AP.04	4-C82-ENV-AQ.04 Effluent Air Radioparticulate Sampler Calibration	0*	06/01/94				
* This document is a complete revision of document 5-21000-OPS-AP.04,R0.							
AP.06	Effluent Air Pilot Tube Inspection and Replacement	t					
AP.08	Volumetric TSP/PM ₁₀ Calibration , Ambient Air Particulate Sampling High Volume Method	0	10/01/91				

ROCKY FLATS ENVIRONMENTAL

TECHNOLOGY SITE

EMD OPERATING PROCEDURES MANUAL VOL. VI: AIR

Manual No.:

Procedure No.:

Page:

Effective Date: Organization:

5-21000-OPS-AP

Table of Contents, Rev 7 2 of 2

09/28/94

Environmental Management

Procedure No.	Title	Rev. No.	Effective <u>Date</u>
AP.09	Ambient TSP/PM ₁₀ Air Particulate Sampling High Volum Method	n e 0	10/01/91
AP.10	Radioactive Ambient Air Monitoring Particulate Sampling Data Reduction	0	10/01/91
AP.11	Mass Flow TSP/PM ₁₀ Calibration, Ambient Air Particulate Sampling High Volume Method	0	10/01/91
•AQ.11	4-D21-ENV-AQ.11 Air Emissions Reporting and Permitting for New and Existing Sources	0	07/06/93

This procedure will be replacing AP.11. The procedure, AP.11, will be combined with the procedure, AP.08, be renamed AQ.08, and be placed inside this manual. This document, AQ.11, was issued with a limited distribution list. It can be requested as a stand-alone, or as part of the entire manual.

AP.12	Placement, Design, Installation, and Operation of Meteorological Monitoring Stations		
AP.13	Radioactive Ambient Air Monitoring Program	0	10/01/91
AP.14	Meteorology Data Downloading		
AP.15	Restoration Projects Data Reduction for Radioactive Ambient Air Monitoring	0	10/01/91
AP.16	4-D31-ENV-AQ.16 Restoration Projects Ambient Air Particulate Sampling (High Volume Method)	0*	05/26/94
*This documen	t is a complete revision of 5-21000-OPS-AP.16,R0.		
AP.17	Sampling Procedure, Volatile Organic Compounds Method TO-14	0	10/01/91
AP.18	Sampling For Organochlorine Pesticides and Polychlorinated Biphenyls in Ambient Air (SVOD)	0	10/01/91

				DC	OÇUMEN	T MODIFI	CA	TION REQU	EST (D	MR)	PAGE 1	1 of
Print or T	ype A	ii Info	mation (Ex	cept \$i			P	09/02/94	ı	5. DMR No. 94-		
2. Edeling Document Number/Flevision 4-698-ENV-AQ.03 C. 33					nt Number II R le to be	ohanged with	this Revision					
4. Originator's Name/Phone/Pager/Location L. C. Pauley/3943/3838/030				Effluent Air	Radio	particulate	Sample	e Collection				
6. Dooument T	Abe D	Proces	dure	7. Docum	nent Modification T	you (Check only one	har	nge X Noninten	Change	☐ Editorial C	Correction	☐ Cancellation
8. Ham 9. Pa	10.	Step.		17.40	110131			odfloatiant	· Onange	— Luitorar c	7011000011	- Curionation
1 14 8.3 Change [1] to: Deliver the samples and completed Appendixes to the Building 123 Analytical Laboratory receiving station in accordance with the Rocky Flats Transportation Safety Manuals.												
2 1	4 [5]	Delete st	ep.								
		•	ļ		1							
	-				:							
					1							
24:		انتزنت		* *,	,	erromano em el maja	44-4.0	Na. a see	Ĭ			to the second of
	1											
12. Justification	(Reason	1 for Mod	Ification, EJO #,	TP #, etc.)					- 1			
Effluent	Trave	lere s	and Chain	of Cus	tody Sheet	¢ (Annendivi	96)	must be left in t	he lah w	ith the samp	les The	Air Quality
Project r	กลกลถุ	jer wi	Il collect ti	ne App	endixes aff	er the Labor	ato	ry personnel ha	ve alpha	beta counte	d the sa	mples.
	•	:				· · · · · · · · · · · · · · · · · · ·				" · is		•
			1					*				
										ti s		
man di mana di Mana di mana d		* .		. :-		*** * *						
		· · · ·										
# 1		-			*************					· · · · · ·	• • • •	
1		a. 1. ·		11.	* * *	21				1		· ·
					-	::					;	
If modification is	stora nev	v proced	ure of a ravision,	list concu	rring disciplines in I ck 14, and dates in	Block 13, and enter f	√A in	Blocks 14 and 15. If mod	ritestion is for	any type of change o	or a cancellato	on, organizations
13. Organization												15. Date (if applicable)
SME			_/S/	L	C. Pa	uley	_					928/94
Pad Ops	_		JS1_			1009-						9127194
	rester		NI	! /	ser te	lecan is	!/	OME &	ر ک	10-10-90	<u> </u>	
	+-											
	+											
. / / · ·	1	-										
(6. Orbrinshota	Burnarias	e (oxinta	(cry/date)					0/1/-1		·		
H. C.				2-14	wy	110 0-05		9/6/24	100 5	Complete Co	a las ru-	No Poto
17. Assigned Sh	TG!	A EV	ocation			18. Coet Center 418	_	19. Charge Number 98660312		23/94	21 Effect	7194_
2. Accelerated	Heview?	- 1	23.ONG Re	vlew	Not r	escrised	2	724.	9-26		\sim	
24. Flaspooreible Manager (print styr), date) Rut Cuit 9/6/Pht 9/27/94												
AV. CO. C. J.												
RF-47940	(5/93)	•							,,	BYYE	9.2	ATONIUCH WILL
								118.		DATE	7	74

COMMITTE CLASSIFICATION DEVICE WAIVER 12.003. HOWELMAN, CLASSIFICATION OFFICE JUNE 11, 1031

EFFLUENT AIR RADIOPARTICULATE SAMPLE COLLECTION

09/27/94

4-C83-ENV-AQ.03 REVISION 0 PAGE,2

LIST OF EFFECTIVE PAGES

Pages	Effective Date	Change Number
1-13	05/09/94	
14	09/27/94	94-DMR-001845
15-31	05/09/94	

TOTAL NUMBER OF PAGES: 31

94-DMR-001845

EFFLUENT AIR RADIOPARTICULATE SAMPLE COLLECTION

09/27/94

4-C83-ENV-AQ.0 REVISION 0 PAGE 14

6.2 Sample Collection (continue)

- [24] IF flow CANNOT be regulated, THEN notify the supervisor.
- [25] Inspect the associated system components for integrity.
- [26] Record any deficiencies on the appropriate appendix, and notify the supervisor.
- [27] IF sample locations remain to be exchanged, THEN repeat Steps 6.2[3] through 6.2[26].
- [28] Review the appropriate appendix for accuracy and completeness.
- [29] Verify the accuracy of the appropriate appendix, and document on the appropriate appendix.

6.3 Sample Disposition

RCT

[1] Deliver the samples and completed Appendixes to the Building 123 Analytical Laboratory receiving station in accordance with the Rocky Flats Transportation Safety Manuals.

Analytical Laboratory Technician

[2] Verify that the number of samples received is equal to the number recorded on the appendix, and document on the appropriate appendix.

RCT

- [3] Pick up the empty sample tube carriers and the brass rings from the previous sample collections.
- [4] Return the empty sample tube carriers and the brass rings to the supply storage area.